
ommander's Hazard Identification

Ground Operations & Equipment













Road Identified As One Way Not Enforced By Uni This Put Operator In A Misjudgment Situation. Slide One



Trailer Combination Unsafe For Road Use.

Tractor Also cannot pull M872 Max Load Capacity


Slide Two



Trailer Rear Wheelfrailer Front Wheelking Pin Failure:
Has To Much Has Not Enough King Pin Not Level
Pressure For Brakeressure For Brake On 5th Wheel, Also
Effects Braking and Steering Additional Pressure







5 Ton Truck Davi

2nd Safety Pin Not In

Davit Is Ready Fall Out & Off When Vibrated Dropoed On A V Load Of Kids



